

SERVICE BULLETIN

JUNE 1995

KART-0005

WARNING PLASTIC FUEL TANK BULLETIN

Warning: Fuel tank vent being plugged or restricted resulting in fuel vapor expansion, distorting fuel tank.

This can cause the tank to bulge and in extreme cases contact the go-kart engine muffler protector. If this should occur the plastic fuel tank can become softened and could result in a rupture.

Check fuel tank caps for proper venting on a regular and frequent basis. Beware of any bulging of all plastic compound fuel tanks, regardless of application.

If you have any questions please call service at (800) 854-3140 or (503) 304-



4897 Indian School Rd NE
Salem, Oregon 97305
(800) 854-3140
FAX (503) 304-1899

Inside: Plastic Fuel Tank Service Bulletin..

