

SERVICE BULLETIN

March 11, 1996

Thunder-04

Hinge Mount Update

AFFECTED MODELS


ThunderBolt go-karts sold between December 1, 1995 to January 6, 1996

SYMPTOM

Cracking developing on body support.

CORRECTIVE ACTION

Install new update bracket. *See instructions right.*



Using the update bracket as a template, mark holes to be drilled. Drill marked holes using a 17/64 drill bit.

Using hardware supplied, bolt bracket as seen in picture right.

Warranty: *The normal warranty applies. Updated parts are ship with this bulletin at no charge.*