

SERVICE BULLETIN

AUGUST 1995

GO-KART DEFLECTOR UPDATE

AFFECTED MODELS

Go-Karts equipped with exhaust deflector comps.

SYMPTOM

Excessive heat between muffler and protective shield causing fuel tank to get soft and may rupture.

PROBABLE CAUSE


Missing Guide.

CORRECTIVE ACTION

Install Guide as seen in picture.

Guide, Muffler **Part#34407320**

Updated parts will be sent at no charge.



Call (800) 854-3140 or (503) 363-7533 if you have any

J&J Amusements, Inc.
A Corporation of Oregon

2315 Pringle Road SE
Salem, Oregon 97302
(800) 854-3140
FAX (503) 363-7885



Inside: Go-Kart Muffler Service Bulletin..