




Issuing Entity:
J&J Amusements
4897 Indian School Road NE Ste. 150
Salem, Oregon 97305-1126
United States
Phone: 800-854-3140 Fax: 503-304-1899
(outside U.S.) Phone: 503-304-8899

Bulletin No: Seatback09
Release Date: 5/01/2009
Effective Date: 5/01/2009
Supersedes: N/A
Completion Date: 5/01/2009
Page: 1 of 1

SAFETY ALERT

Ride Manufacturer: J&J Amusements, Inc	Affected production dates: All
Ride Name: J&J Go Karts	Affected Serial Numbers: All
Model Number: All accept Viper, Scorpion & Sidewinder	
Abstract Of Issue: Under severe impact the steel seat back portion of the go-kart frame can become bent forward. This can cause an excess gap between the seat and the roll bar.	
Reason For Release: This gap can constitute a hazard	
Action To Be Taken: If the steel seat back has been damaged contact J&J parts department for an update parts kit. This kit will be provided and shipped to you free of charge. Please advise how many kits (1 per go-kart) are needed. Seatback Reinforcement kit (#1-99-A0003)	

Detail of Issue:



This illustration shows an extreme gap between the seat back and roll bar and would be a hazard.